

Existing conditions at the project area include concrete rubble, sculpted and colored soil nail walls constructed as emergency repairs in 2004 (lower left-hand corner of picture), white protective railing around areas of failed roadway, nonnative vegetation and minimal beach area due to the concrete rubble and rock riprap.

Existing Conditions, Bluff View
Santa Cruz, California

R: New\11762\Figure5-1a 03-27-06 rYE